

15 pin vacuum feedthru for pulser		
External male	Internal cables	Function
1	coax 1 center cond.	plane A, wires 0-24
9	coax 1 shield	plane A, wires 0-24
2	coax 2 center cond.	plane A, wires 25-49
10	coax 2 shield	plane A, wires 25-49
3	coax 3 center cond.	plane B, wires 0-24
11	coax 3 shield	plane B, wires 0-24
4	coax 4 center cond.	plane B, wires 25-49
12	coax 4 shield	plane B, wires 25-49
5	coax 5 center cond.	plane C, wires 0-24
13	coax 5 shield	plane C, wires 0-24
6	coax 6 center cond.	plane C, wires 25-49
14	coax 6 shield	plane C, wires 25-49
7	coax 7 center cond.	spare cable
15	coax 7 shield	spare cable
8	outer braid shield	Outer common shield